

CITY of ORONO

Municipal Offices

Street Address: 2750 Kelley Parkway Orono, MN 55356 Mailing Address: P.O. Box 66 Crystal Bay, MN 55323-0066

To:	The Current Owner of Address	2685	Copperview
City insp addr sket	Ordinance requires that onsite sewag ected on a periodic basis. The onsite ress has been inspected and the followich of the known components of the sy Orono City Hall.	e treatment sys sewage treatm ing is known a	stems in Orono be ent system at the above about the system. A
If you day:	ninent Public Health Threat Yes No es, please contact the Onsite Systems s of receipt of this notice. The septic s nin 90 days. Failure to do so will result action.	system must be	e brought into compliance
If y	tem Identified as Non-Compliant Yes No es, system must be brought into comp December 31, 2007 December 31, 2010 Other	liance by:	
The	otic Tank(s) Pump out Needed Yes No City recommends the septic tank(s) a every three years. City records indicate through the inspection pipes, this allowed through the inspection pipes, this allowed through the inspection pipes.	ate the tank(s) ld be cleaned t	were last pumped out on hrough the manhole and
	4) De 271	Data of In	onaction 5-06



6-25-04

To Current Owner:

CITY of ORONO

Municipal Offices

Street Address:

952-249-460 Mailing Address:

Address: 2685 Copper View Dr.

Matt Bolterman - Septic System Inspector

2750 Kelley Parkway Orono, MN 55356 P.O. Box 66 Crystal Bay, MN 55323-0066

City Ordinance 199 requires that each existing on-site sewage treatment system in Orono be inspected every two years. The on-site sewage treatment system at the above address has been inspected and appears to fall into the categories checked below. SYSTEM CONFORMITY (1-3): 1 "CODE SYSTEM" An ISTS which meets all the location, design and construction standards of the current Orono Municipal Code. "COMPLIANT SYSTEM" An ISTS which does not meet all the location, design and construction standards of the current Orono Municipal Code but does meet the three foot separation requirement or two foot requirement for systems installed 1996 or earlier, and which is not failing or an imminent threat to public health or safety. "NON-COMPLIANT SYSTEM" A prohibited ISTS; an ISTS located within a designated 100-year flood plain, any ISTS which may or may not meet all the location, design, or construction standards of the current Orono Municipal Code and which is failing for any reason; and any ISTS with less than three feet of unsaturated soil or sand between the distribution device and the limiting soil characteristics. TANK CONDITION (5-7): Tank inspection indicates: Pumpout not needed at this time. Septic tanks must be pumped out this year (city code recommends tanks to be pumped out once every 3 years. Tank was last pumped 2003 Make sure septic tanks are pumped through manhole and not through white inspection pipes. This allows for the proper cleaning. Keep water softner and iron filter discharge out of septic system to prolong life of drainfield. Ask pumper to test alarm float to verify alarm is still working in your house. The alarm warns owner that septage is about to backup into basement. Inspection risers missing-tanks could not be inspected. Inspection risers (4" dia. pipe) must be installed in each tank. If tanks have not been pumped out within the last three years, they should be pumped out now. DRAINFIELD CONDITION (8-10): (8) Drainfield is dry, no surfacing evident. 9 Some evidence of surfacing, not critical yet. 10 Drainfield is saturated and visibly discharging untreated effluent to the surface. Contact the City Inspector immediately. Repairs must be completed within 90 days. COMMENTS: Mourd

Note: In the event that this inspection report is used to satisfy the requirements for a mortgage or other transfer of property, be advised that this report does not guarantee or certify that an existing system will continue to function properly, but is merely an opinion of the adequacy of the system under current conditions based on the available information.



CITY of ORONO

Municipal Offices

Street Address: 2750 Kelley Parkway Orono, MN 55356 952-249-4600

Mailing Address: P.O. Box 66 Crystal Bay, MN 55323-0066

To Current Owner:

Address:	2685	Copper	Vien	Dr.	

City Ordinance 199 requires that each existing on-site sewage treatment system in Orono be inspected every two years.

The on-site sewage treatment system at the above address has been inspected and appears to fall into the categories checked below.

_	
 "COMPLIANT SYSTEM" An ISTS which does not Code but does meet the three foot separation requirement an imminent threat to public health or safety. "NON-COMPLIANT SYSTEM" A prohibited IS or may not meet all the location, design, or construction. 	tion, design and construction standards of the current Orono Municipal Code. It meet all the location, design and construction standards of the current Orono Municipal cent or two foot requirement for systems installed 1996 or earlier, and which is not failing or STS; an ISTS located within a designated 100-year flood plain, any ISTS which may on standards of the current Orono Municipal Code and which is failing for any reason; and or sand between the distribution device and the limiting soil characteristics.
Make sure septic tanks are pumped through man This allows for the proper cleaning.	
DRAINFIELD CONDITION (8-10): 8 Drainfield is dry, no surfacing evident. 9 Some evidence of surfacing, not critical yet. 10 Drainfield is saturated and visibly discharging immediately. Repairs must be completed within	untreated effluent to the surface. Contact the City Inspector in 90 days.
OMMENTS: Mound and to	anks look ok.
7-8-02	man Botternan
Date of Inspection	Matt Bolterman - Septic System Inspector

Note: In the event that this inspection report is used to satisfy the requirements for a mortgage or other transfer of property, be advised that this report does not guarantee or certify that an existing system will continue to function properly, but is merely an opinion of the adequacy of the system under current conditions based on the available information.